# Restore Tool Manual

The tool "Restore" is used to return the factory parameters to any device in the "Panther 3.0" line, either IP camera or HVR.

Note: For HVRs with firmware after 2016.11.28, you must use the "V2" of this tool.
The HVR with previous date will continue using the previous tool "V1"

Mode of USE:

1. Double click on the executable (Restore.exe).

2. Enter the IP of the equipment to be restored.

3. Press the "Search" button to select the listed equipment (if it does not appear continue).

4. Check the box "Restore"

5. Click on "OK", a new confirmation window will be presented.

6. After this restart the device.